


1


FIG. 1 3 Wet Coat Integrated Two Tone Paint Process




Total of 5 Coating Steps and 2 Bakes

FIG. 2

Conventional Iwo Tone Paint Process



Total of 6 Coating Steps and 3 Bakes



;